

Report on E2 Lock Losses

David Chin, Dick Gustafson Keith Riles
(University of Michigan)

Masahiro Ito
(University of Oregon)

Bill Butler
(Rochester University)

Background Information

- **Coarse tidal actuation disabled during E2**
 - » Expect periodic lock losses as dynamic range exceeded
 - » Rate of lock loss determined by linear combination of common-mode and differential-mode tidal slopes
(steep slope -> short locked stretches)
- **Pitch compensation reduces effective range
(must push harder with upper coils)**
- **Residual mirror imbalances require DC offsets in coil currents**
 - » Asymmetry leads to saturation sooner in one direction

Background Information

- **Data taken in recombination configuration (no recycling) and with individual arms**
- **Actuation configuration:**
 - » **L+ -- Equal push on ETMX and ETMY**
 - » **L- -- Opposite push on ETMX and ETMY**
 - » **I- -- Opposite push on ITMX and ITMY (and ETMX/ETMY)**

Observations

- **Lock durations:**
 - » Recombination locks lasted typically an hour
 - » Qualitative correlation of lock length with slope confirmed
 - » But lock lengths shorter when CM tidal slope falling, suggesting asymmetric sensitivity (see figure)
- **Y arm behavior:**
 - » Transmitted light thru Y arm drifted linearly with time, suggesting misalignment steadily worsening
 - » Optical levers for both pitch and yaw confirmed drift
 - » Interpreted as mistuning of pitch compensation and yaw balance
 - » ETMY output matrix retuned on 4th day, giving smaller drifts

Observations

- **X arm behavior:**
 - » Transmitted light thru X arm fairly flat during locks (well-tuned output matrix)
 - » But rapid, non-linear degradation seen just before lock loss
 - » Yaw of ETMX showed modest, linear drift
 - » Pitch flutter, but same rapid, pre-loss degradation
 - » Two coils on ETMX with large DC offsets
 - » Symptoms suggest “premature” saturation in one or more ETMX coils, causing mirror twist, light degradation and loss of servo gain

Observations

- **Coil currents**

- » Examined trends of ETMX and ETMY and found anomalous behavior in upper left (UL) coil of ETMX:
 - “Software rails” seen in data acquisition ADC at expected +/-2 Volts for all ETMX, ETMY coils
 - But just before lock-loss, evidence of “hardware rail” seen in ETMX UL (Odd, symmetric, exponential decay of min/max envelope, suggesting internal electronic saturation in UL circuit (see figure))
 - During one such “decay” checked monitor points on ETMX controller (mid station) with portable oscilloscope. Observed severe, asymmetric railing at +2 V on UL, moderate railing on UR, almost none on LL and LR.
 - Railing much reduced once lock lost and reacquired
 - Power spectrum of ETMX UL coil current anomalous

Conclusions on Saturation

- **Necessity of tidal actuation confirmed!**
- **Premature saturation in UL coil very likely (some coil has to go first, but this behavior seems pathological - faulty circuit?)**
- **Some observations hampered by AC coupling of DAQ to coils (but not relevant to scope readings)**
- **New improved controller design installed on one mirror at LHO and in pipeline for others**

Other Work

- Complete list of lock stretches (>1 minute) can be found on team web site
(from **Dave Chin's** DMT lock transition monitor)
- **Masahiro Ito's** glitch monitor identified four distant earthquakes (Montana, Tonga, Peru, Japan) correlated with lock losses during E2