




Commissioning Progress and Plans Hanford Observatory

LSC Meeting, March 21, 2005
Stefan Ballmer

“Typical” noise midway through S4

LIGO Mid S4 Noise




*T0=14/03/2005 06:00:00


*Avg=20/Bin=5L

*BW=0.187493

Increasing the laser power




- With TCS Annulus heating we achieved optimal recycling gain
 - H1 Inspiral Range up to 8.5Mpc (back in Aug 2004, 4 Watt into MC)
- But:
 - Not stable over time because effective lens changed slowly ($T_{1/e}=4h$)
- Solution:
 - Implemented servo using Bull's eye detector on POB path and AS_I signal
 - This kept the recycling gain at maximum
 - But not enough TCS actuation range for long time operation a 4 Watt.
 - ❖ H1 at 3 Watt into the MC for S4



H1


Thermal lensing




- Indirect measurement of absorbed power in H1:
 - Run H1 at different power levels
 - Let TCS Servo compensate

- Result:
 - DC offset due to beam splitter curvature
 - ~3 mWatt / Watt expected for ~1ppm coating absorption
 - 50 mWatt / Watt for ITMX
 - 19 mWatt / Watt for ITMY


- But which optics are bad?




H1 Noise Sources



H2: Sensitivity progress




Hanford 2km Progress




*Bin=5L
LIGO I

H1 and H2: Accomplished since last August




- New actuation electronics (DAC / Dewhitening / Coil Driver)
- New Table Top FSS (800 kHz bandwidth)
- Installed new MC / CM board (100kHz / 45kHz bandwidth)
- WFS head simplified (more RF gain / no oscillation)
- 1-FSR (37kHz) and 100kHz channel readout implemented
- IOT EO shutter replaced with fast shutter
- Equi-Tech balanced power installed (all End's, Mid's and DC power supplies in LVEA)
- New TCS Chillers
- Some front-end code changes:
 - ❖ gain ramping (nice!)
 - ❖ LSC to ETM SUS timing improved
 - ❖ ...
- Photon calibrator: Tested on EX

H1: Accomplished since last August




- New ISS installed (100kHz bandwidth)
- Micro-seismic feed-back system installed
- Mitigation of TCS intensity noise
- Auxiliary loops running on POX + POY (more power)
- Non-Resonant sideband REFL detector running (no improvement)
- 2nd generation OMC testing (Keita) (still beam jitter noise limited)

Accomplished since last August




- All 4 AS photodiodes + electronics installed
 - A whole series of small electronics modifications copied from H1.
 - Auxiliary loop bandwidth increase
 - TCS system installed (but H2 already was close to max recycling gain)
 - Moderate power increase (1.4 Watts into the MC)
-
- But sometimes the biggest sensitivity improvement steps come from eliminating goof-ups...

Main Task After S4 Hanford 4 km (H1)



- Continue with excessive absorption study
 - ❖ Is it 1 bad optic or multiple optics?
 - ❖ Which optics?
 - ❖ What is bad (surface absorption / bulk absorption)?
 - Methods:
 - ❖ FLIR camera imaging of heating optics (expect $\sim 1^\circ\text{C}$ / Watt absorbed)
 - ❖ Spot size vs. heating for various interferometer ports
 - ❖ Witness sample and spare optics characterization
- 2 possible approaches:
 - Replace one / multiple bad optics
 - Increase TCS actuation range (more power / TCS for BS)
- Aim for decision in 3rd week of April

Main Task After S4 Hanford 2 km (H2)




□ Power increase

- Follow up on pre-S4 attempts
- Refurbish Lightwave laser (currently at 4.5 Watt max)
- AS_I range problem

□ Finish catching up to H1 / L1

- Install new ISS
- Install 29MHz Crystal Oscillator (ordered, expected in April)
- New low noise RF distribution system

Other Task After S4 all interferometers



- Assess environmental sensitivity (mainly seismic and acoustic)
 - ❖ Low-loss optics for ISC tables
 - ❖ Additional enclosures?
 - ❖ Floating ISCT tables?
- 60 Hz mitigation (We can't ignore it any longer...)
- More AS port photo detectors / more AS_I correction range
- Lock resonant / non-resonant sideband oscillators / RF distribution
- OMC tests on L1 and H2
- New timing system
- Remote Optical lever / transmission QPD centering
- PMC replacements
- Install all Photon Calibrators