



G960166- 01 - O-P

1. Southwest Arm at station 38+00 Installing 24in. RCP Pipe balance line between ditches.

G960166- 02 - O-P

2. Southwest Arm at Station 38+00 looking northeast at trench.



G960166- 03 - O-PV

3. Standing at construction site yard looking southeast at Apex area and result of a storm.





G960166- 04 - O-P

4. Stranco equipment waiting on bench for the game to start.

G960166- 05 - O-PV

5. Apex area showing effects after rain shower.



G960166- 06 - O-P

6. Apex area showing clearing after the storm.



G960166- 07 - O-P

7. Stranco equipment being serviced and awaiting for conditions to be favorable to start work.

G960166- 08 - O-P

8. Apex area looking southeast at soil conditions after working the drying process.



G960166-09 - O-P

9. Apex area looking southwest at Arm #2. The soil is being dried.



G960166- 10 - O-PV

10. Apex area showing the plastic sleeve for one of the settling plates.

G960166- 11 - O-P

11. Apex area showing rain just starting “see clearing spot in clouds upper left corner.”



G960166- 12 - O-P

12. More rain.

