

Change Summary:

1. A wire was added from P1-9A to U5-4 to implement the blanking feature.
2. The 1/2 PS Offset circuit formed by U13C is not used.
3. There is a known gain problem with U2 being in an inverting configuration.
4. The mixer output to DAQ is now wired to P2-7A and P2-7C, hot/gnd respectively, instead of J10
5. The actuator drive to DAQ is now wired to P28A and P2-8C, hot/gnd respectively, instead of J10

Changes accomodating 9 KHz resonance

Component	Was	Is	Implements
C11	0.1UF	1UF	2 Hz pole
C12	6.8NF	47 NF	425 Hz zero
C25	0.01UF	0.1UF	10 Hz pole
C26	51PF	3.2NF	8.9 KHz Notch

