



Change Summary:

1. R16 and R27 must have a 1nF capacitor in parallel.
2. D1 & D2 are not installed.
3. C18, C40, C44, C62, C64, C80 are polycarbonate.
4. U24 (-5V Regulator) faces the opposite direction to the other regulators (U12, U16, U17).
5. DAQ Connections have been added to board:
 - a. Mixer error - P2-1A, P2-1C, Hot/GND respectively
 - b. Fockels Cell Drive - P2-2A, P2-3C, Hot/GND respectively
 - c. Slow Actuator - P2-3A, P2-3C, Hot/GND respectively
 - d. Fast Actuator - P2-4A, P2-4C, Hot/GND respectively

