



G960024-01-O-P

1. Site visit by Congressman Richard Baker from left to right, Skip Smart, Congressman Baker, Mayor Dale Erdey & Bo Garrison, former head of the State Police

G960024-02-O-P

2. Congressman Baker and visiting group with the southeast arm in the background.



3. Installing 60" culvert pipe at crossing 44+60, Southwest arm.

G960024-03-O-P



G960024-04-O-P

4. Southwest arm , at Station 60+00, installing 60" culvert pipe.

G960024-05-O-PV

5. Southwest arm at Station 60+00 getting ready to start backfilling.



6 Southwest arm at station 60+00 starting to backfill

G960024-06-O-P





G960024-07-O-P

7.Southwest arm at station 9+50 showing cross section of backfill

G960024-08-O-P

8.Southwest arm at station 9+50 a section of replacement pipe.



9.Southwest arm at station,44+60 the access road down the center of right of way

G960024-09-O-P



G960024-10 -O-P

10. Southwest arm at station 44+60 showing culvert pipe being prepared for backfill



G960024-11 -O-P

11. Southwest arm at station 44+60 showing the ends of pipe



12. Southwest arm at station 60+00 showing cross section of backfill

G960024-12 -O-P



G960024-13 -O-PV

13. Southeast arm about station 113 looking north, disking berm

G960024-14 -O-PV

14. Southeast arm at station 115+00 looking south at disking berm material to remove moisture.



15. Southeast arm at station 112+00 dozing organic material to the side.

G960024-15 -O-P



G960024-16 -O-P

16.Southeast arm at station 112+00 showing organic material

G960024-17 -O-PV

17.Southeast arm at station 111+00 a closer look at the organic material



18.Southeast arm at station 118 looking north showing contrast of organic material

G960024-18 -O-P



G960024-19 -O-P

19. Southeast arm at station 112 looking northeast, compacted berm.

G960024-20-O-P

20. Southeast arm at station 115 showing a close up of removing organic material.



No print or negative received.

21. Southeast arm removing unacceptable material. ;as in previous photo.

G960024- -O