



G960155-01 - O-P

1. Installation of fired ends on 72" culverts at Sta. 16+40 on Southwest Arm.

G960155-02 - O-P

2. Stockpiled riprap and precast concrete cutoff walls for culverts at Sta. 16+40 on Southwest Arm.



G960155-03 - O-P

3. Application of geotextile fabric on inlet side of culverts at Sta. 16+40 on Southwest Arm.

G960155-04 - O-P

4. Settlement monitoring plate being installed on Southeast Arm End Station. {Placed at elev. 51.0'}.



G960155-05 - O-P

5. Settlement monitoring plate on Southeast End Station. (Partially backfilled).



G960155-06 - O-P

6. Completed installation of culverts (outlet end) at Sta. 44+60 on Southwest Arm.



G960155-07 - O-P

7. Installation of settlement monitoring plate at Corner Station.

G960155-08 - O-P

8. Disking of fill at Sta. 5+00 on Southeast Arm.



G960155-09 - O-P

9. Excavating, placing and spreading fill material at Sta. 82+00 on Southeast Arm. (Looking South).



G960155- 10 - O-P

10. Looking South on Southeast Arm End Station. Finish grade stakes set.

G960155- 11 - O-P

11. Rain clouds building!!



G960155- 12 - O-P

12. Dumping and spreading fill at Sta. 86+00 on Southeast Arm. (Looking North).

G960155-13 - O-P

13. Grade stake at Sta. 68+00 on Southeast Arm. (Fill at finish grade).



G960155-14 - O-P

14. Grade stakes at Sta. 70+00 on Southeast Arm. (Fill at finish grade).



G960155-15 - O-P

15. Looking North on Southeast Arm at Sta. 60+00. Fill smooth rolled to seal surface before imminent rain.





G960155- 16 - O-P

16. Fill compacted by sheepsfoot roller at Sta. 85+00 on Southwest Arm. (Looking West).

G960155-17 - O-P

17. View from North side of Corner Station looking South after rain.



G960155- 18 - O-P

18. View from East bank of Lake LIGO. (Former site access road at Corner Station).



G960155- 19 - O-P

19. Idle equipment.
"Stuck" water truck
presently not needed.

G960155- 20 - O-P

20. Looking Southwest
across Corner Station
after another rain.



G960155- 21 - O-P

21. Looking Southeast
from North side of
Corner Station.

G960155-22 - O-P

22. A view of wet conditions from North side of Corner Station looking East.



G960155- 23 - O-P

23. Looking West at access road through Corner Station. (Tide still in).



24. Operator Error.