





NOTES CONTINUED:
 ⑤ SCRIBE, ENGRAVE, OR MECHANICALLY STAMP (NO INKS OR DYES) DRAWING PART NUMBER AND REVISION ON NOTED SURFACE FOLLOWED ON THE NEXT LINE BY A THREE DIGIT SERIAL NUMBER. SERIAL NUMBERS START AT 001 FOR THE FIRST ARTICLE AND PROCEED CONSECUTIVELY. USE .07" HIGH CHARACTERS. EXAMPLE: DXXXXXXX-VY, S/N 001. A VIBRATORY TOOL MAY BE USED.

⑥ MACHINE ALL SURFACES.



REV.	DATE	DCN #	DRAWING TREE #

NOTES AND TOLERANCES: (UNLESS OTHERWISE SPECIFIED)

1. INTERPRET DRAWING PER ASME Y14.5-1994.
2. REMOVE ALL SHARP EDGES, R.02 MIN.
3. DO NOT SCALE FROM DRAWING.
4. ALL MACHINING FLUIDS MUST BE FULLY SYNTHETIC, FULLY WATER SOLUBLE AND FREE OF SULFUR, SILICONE, AND CHLORINE.

DIMENSIONS ARE IN MILLIMETERS
 GENERAL TOLERANCE ± 0.1
 ANGULAR $\pm 0.2^\circ$

MATERIAL	ALUMINIUM	FINISH	1.6 μm
-----------------	-----------	---------------	-------------------

LIGO CALIFORNIA INSTITUTE OF TECHNOLOGY
 MASSACHUSETTS INSTITUTE OF TECHNOLOGY

SYSTEM	ADVANCED LIGO	SUB-SYSTEM	SUS
NEXT ASSY			

PART NAME				FIBRE GUARD SEPERATOR			
DESIGNER	L CUNNINGHAM	28/06/10	SIZE	DWG. NO.	D0902508	REV.	V2
DRAFTER	L CUNNINGHAM	30/06/10	c				
CHECKER							
APPROVAL			SCALE: 1:2	PROJECTION:		SHEET 1 OF 1	