




NOTES CONTINUED:

⑤ SCRIBE, ENGRAVE, OR MECHANICALLY STAMP (NO INKS OR DYES) DRAWING PART NUMBER AND REVISION ON NOTED SURFACE FOLLOWED ON THE NEXT LINE BY A THREE DIGIT SERIAL NUMBER. SERIAL NUMBERS START AT 001 FOR THE FIRST ARTICLE AND PROCEED CONSECUTIVELY. USE .07" HIGH CHARACTERS. EXAMPLE: DXXXXXXX-VY, S/N 001. A VIBRATORY TOOL MAY BE USED.

⑥ MACHINE ALL SURFACES.

REV.	DATE	DCN #	DRAWING TREE #



NOTES AND TOLERANCES: (UNLESS OTHERWISE SPECIFIED)	
1. INTERPRET DRAWING PER ASME Y14.5-1994. 2. REMOVE ALL SHARP EDGES, R.02 MIN. 3. DO NOT SCALE FROM DRAWING. 4. ALL MACHINING FLUIDS MUST BE FULLY SYNTHETIC, FULLY WATER SOLUBLE AND FREE OF SULFUR, SILICONE, AND CHLORINE.	
DIMENSIONS ARE IN MILLIMETERS TOLERANCES: .XX ± 0.10 .XXX ± 0.010 ANGULAR ± 0.2°	MATERIAL 6061-T6 Al FINISH 1.6 µm

CALIFORNIA INSTITUTE OF TECHNOLOGY MASSACHUSETTS INSTITUTE OF TECHNOLOGY	
SYSTEM ADVANCED LIGO	SUB-SYSTEM SUS
NEXT ASSY	

PART NAME FIBRE REMOVAL BLADE			
DESIGNER L CUNNINGHAM	DATE 07/07/10	SIZE c	DWG. NO. D1001690
DRAFTER L Cunningham			REV. v2
CHECKER		SCALE: 1:2	PROJECTION:
APPROVAL			SHEET 1 OF 1