

- STEEL OR OTHER SOURCES OF CONTAMINATION DURING MOVING, WORKING, AND STORAGE. COVER CARBON STEEL WITH SST OR HEAVY PAPER, AND KEEP PLATES AND ROLL-UPS WRAPPED OR COVERED AT ALL TIMES WHEN NOT BEING PROCESSED.
- 8. A 2"X12" COUPON OF MATERIAL FROM THE SAME LOT OF MATERIAL MUST BE PROVIDED WITH EACH PIECE.
- ETCH THE HEAT/LOT NUMBER AND PART NUMBER WITH A VIBRATORY TOOL WITH MINIMUM TIP RADIUS OF .005"



CORPORATION SCIENTIFIC AND INDUSTRIAL EQUIPMENT

> 3200 DWIGHT RD. SUITE 100 ELK GROVE, CA 95758 916-395-3003 FAX: 916-395-3363 WWW.GNBVALVES.COM

> > **REV**

D

ROLL-UP, ADAPTER A-18, SMALLER

6/14/10 DWG. NO. A 114321-00S DO NOT SCALE DRAWING SCALE: 1:24 SHEET 1 OF 1

3

2