




Revision History	
Rev.	Description
B	Add output resistors R5, R6, R7, R8



NOTE:
DB 15 CONNECTOR MOUNTED ON SIDE OF PD BOX.
CONNECTED TO IDC 16 CONNECTOR MOUNTED ON
BOARD
VIA MASS TERMINATION CABLE.

IDC Pin # / D Conn Pin #

1 / 1
2 / 9
3 / 2
4 / 10
5 / 3
6 / 11
7 / 4
8 / 12
9 / 5
10 / 13
11 / 6
12 / 14
13 / 7
14 / 15
15 / 8
16 / NC

