



Fast Poles: 10Hz, 100Hz, 20 kHz
 Fast Zeros: None
 PC Poles: 1Hz, 2Hz, 3Hz
 PC Zeros: DC, 100kHz

Zero at DC
 Pole at 3kHz
 Pole at 2kHz

Zero at 100kHz
 Pole at 1kHz

Noise Gain Compensation Network

