



Fast Poles: 10Hz, 10kHz, 20 kHz
 Fast Zeros: None
 FC Poles: 1kHz, 2kHz, 3kHz
 PC Zeros: DC, 100kHz

Pole at 20kHz
 Pole at 10kHz
 Pole at 10Hz

Zero at DC
 Pole at 3kHz
 Pole at 2kHz

Zero at 100kHz
 Pole at 1kHz