

DCN No.	E000241-00-C				
SHEET	1	OF	1		

DOCUME	T CHANG	E NOTICE	E (DCN)							
DOCUMENT No. TITLE (DOC-REV-GP. ID)										
D980536-B-C Frequency Stabilization Servo										
D980535-B-C	PSL Wiring Diagram									
	D980401-00-C PSL Willig Diagram PSL Temperature Box									
D700401-00-C TSL Temperature Box										
CHANGE DESCRIPTION (FROM/TO): D980536-B-C To D980536-C-C For update of schematic and revi										
-										
The PSL Wiring Diagram document, D980535-B-C has been updated in D980535-C-C and should have a new title of PSL Rack Wiring Diagrams. It is no longer needed to specify Hanford 2K on this title as all PSL's are the same.										
D980401-00-C drawing must be removed. The original to this drawing has been lost and the one currently in the DCC is the wrong drawing.										
All document titles for the D980401 and D980400 need to be swapped. D980401 is the PSL Temperature Box, and D980400 is the PSL 80 MHZ VCO										
D980401-A-C, reflects the actual installed hardware and is the most current revision										
REASON FOR CHANGE: Updates to installed hardware and correction of document errors										
ACTION: Incorporate change Attach DCN to drawing(s) Other action (specify):										
DISPOSITION	OF HARDWARE (IDEN	TIFY SERIAL NUME	BERS)	DCN DISTRIBUTIO	N (X=incl. docs)					
No hardware affected (recor	d change only)			X McCarthy Baris						
List S/Ns which comply alre	ady:			$oldsymbol{\mathrm{X}}$ Coyne Lazza $oldsymbol{\mathrm{X}}$ Raab Sande	•					
List S/Ns to be reworked or scrapped: Stapfer Tyler W										
List S/Ns to be built with this change:										
List S/Ns to be retested per this change:										
SAFETY, COST, SCHEDULE, REC	UIREMENTS IMPACT	? <u>X</u> No _ Y	es (If yes, enter Change Re	quest number)					
APPROVALS:		DATE	OTHER APPROVA	LS (specify)	DATE					
ORIGINATOR: R. Abbott		5/9/00								
TASK LEADER: R. Bork		5/9/00								
GROUP LEADER: D. Coyne										
DCC RELEASE:										