



DOCUMENT CHANGE NOTICE (DCN)

DOCUMENT No. (DOC-REV-GP. ID)	TITLE	NEW REV.
D980181-B	SOS Suspension Controller	C

CHANGE DESCRIPTION (FROM/TO): Added resistors Radd1, Radd2, Radd3, Radd4 to terminate unused inputs of MAX333 switches on boards.

REASON FOR CHANGE: Improper termination can cause excess noise in the circuit.

ACTION: Incorporate change Attach DCN to drawing(s) Other action (specify):

DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)	DCN DISTRIBUTION
<input type="checkbox"/> No hardware affected (record change only)	Althouse Barish Coles
<input type="checkbox"/> List S/Ns which comply already:	Coyne Lazzarini Lindquist
<input type="checkbox"/> List S/Ns to be reworked or scrapped:	Lucas Sanders Shoemaker
<input type="checkbox"/> List S/Ns to be built with this change:	Stapfer Tyler Vogt
<input type="checkbox"/> List S/Ns to be retested per this change:	Weiss Whitcomb Young
<input checked="" type="checkbox"/> All boards should be upgraded as operations permit.	McCarthy
<input type="checkbox"/>	Wooley
<input type="checkbox"/>	
<input type="checkbox"/>	

SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT? No Yes (If yes, enter CR (CCB) or TCP (TRB) no.)

APPROVALS:	DATE	OTHER APPROVALS (specify)	DATE
ORIGINATOR: J. Heefner	10/3/01		
TASK LEADER:			
GROUP LEADER: D. Coyne			
DCC RELEASE:			