California Institute of Technology Massachusetts Institute of Technology			DCN No. E030418-00-E			
				of		
DOCUMENT No. (DOC-REV-GP.ID)	TITLE				NEW REV	
D020408-B-E	Double Start Counter Wound Spring Assembly				С	
CHANGE DESCRIP	TION (FROM/TO):					
Added flat for a 5 (D020407-B-E).	5/8 wrench on part Double Start (Counte	rwound Sp	oring Con	nector	
Sheet 3 affected of	only.					
REASON FOR CHA	NGE: ease of installation					
ACTION:	corporate Change Attach DCN to Drawing	s 📙	Other Action (s	pecify):		
DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)			DCN DISTRIBUTION			
☐ No hardware was at	ware was affected (record change only): Barish Coles				Coyne	
☐ List S/Ns which comply already:			Lazzarini Shoemaker	Lindquist Stapfer	Sanders Tyler	
☐ List S/Ns to be reworked/scrapped:			Weiss	Whitcomb	Matherny	
☐ List S/N's to be built with this change: all						
∠ List S/Ns to be retes	eted per this change: all					

SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT? NO YES (If YES, enter CR (CCB) or TCP (TRB) #) APPROVALS: DATE ORIGINATOR: Marcel Hammond 8/14/03 TASK LEADER: Jonathan Kern Brian Lantz GROUP LEADER: Dennis Coyne

DCC RELEASE: