

L190-E980627-00-D

07/01/98 WED 14:51 FAX 504 586 7189

PARSONS

509 37421 PM

004 P. 01

INITIATOR C. Gray
DATE 6/2/98
SERIAL NO. ER-004

ENGINEERING CHANGE REQUEST (ECR)

NEXT ASSEMBLY NO. D972609
CUSTOMER DRAWING NO. D972609
DRAWING TITLE L190 HAM SUPPORT BR
REVISION: FROM _____ TO _____



DESCRIPTION OF CHANGE (Simple Plain, Identify Discrepancies)

Remove both dorsal pins from Pier top plate.
(See drawing)

REASONS FOR CHANGE:

Allow freedom of movement of combiners (on actuator
stack and roller plate) on pier top plate.

IDENTIFY OTHER PARTICIPANTS THAT INTERFERED WITH ABOVE (Required):

INTERFACE	DATE	INITIAL

NOTIFY COGNIZANT DESIGNER: _____

NOTIFY COGNIZANT ENGINEER: _____

APPROVER: _____

Hold Change


07/01/98 WED 14:52 FAX 504 986 7189
L. BO. MANFORD

PARSONS

509 8732179

0005
P.02

SP1 HAM ECR-D4



Do not install pins
(or remove)

<p>HYTEC, INC</p> <p>MEMBER</p> <p>SUPPORT PER</p>	
<p>007200-1</p>	<p>007200 0 of 01</p>