

INITIATOR E.P.

DATE July 7, 98

LIQO-E980634-00-D

ENGINEERING CHANGE REQUEST (ECR)

NEXT ASSEMBLY NO. _____

CUSTOMER DRAWING NO. 972501

DRAWING TITLE HAM Top Assembly.

REVISION: FROM _____ TO Rev a.



HYTEC
INCORPORATED

DESCRIPTION OF CHANGE (Simple Words, Identify Dims if Possible):

- callout (2)(5)(30): change to (2)(5)(38)
- add item (38): DWG D972716 custom vented washer.
- item (5), change from D972715-3 to D972715-1

REASONS FOR CHANGE:

- insufficient clearance to insert top shape coil springs.
- incorrect callout

IDENTIFY OTHER PARTS/GROUPS THAT INTERFACE WITH THE ABOVE (Required):

INTERFACE	RESPONSIBLE PARTY	INITIAL

NOTIFY COGNIZANT DESIGNER: A. Smith.

NOTIFY COGNIZANT ENGINEER: E. Ponslet.

APPROVED: [Signature]