

ISC RACK S1201192 L1- ISC-R1	Chassis Type	D#	S#	NOTES	D1001460-V11
42	RF Patch Panel #10 (2U)		NA		
41					
40	RF Patch Panel #11 (2U)		NA		
39					
38	RF Patch Panel #12 (2U)			Not installed	
37					
36	71 MHz Distribution Amplifier	D1000124	S1000675		
35	24.078 MHz Distribution Amplifier	D1000124	S1000673		
34					
33	79.4 MHz FDD (ALS DIFF) (2U)	D0900605	S1200579	(ALS) to Beckhoff in C2	
32					
31	79.4 MHz VCO (ALS DIFF) (2U)	D0900605	S1200576	(ALS) to Beckhoff in C2	
30					
29	Dual D-Sub Breakout Panel	D1201450	NA		
28	158.8 MHz Frequency Doubler	D1002178	S1000740		
27	158.8/79.4 MHz 2-Ch PF Discriminator	D1002476	S1000766		
26	Demodulator RF Patch Panel	D1201470			
25	79.4 MHz VCO (ALS COMM) (2U)	D0900605	S1200575	(ALS) to Beckhoff in C2	
24					
23	79.4 MHz FDD (ALS COMM) (2U)	D0900605	S1200574	(ALS) to Beckhoff in C2	
22					
21					
20	79.4 MHz VCO (PSL) (2U)	D0900605	S1200580	(PSL) to Beckhoff in C2	
19					
18	158.8 MHz Frequency Doubler	D1002178	S1000739		
17	24.078 MHz Dual Delay Line	D0900128	S1103423		
16	24.078 MHz 2-Ch Demodulator	D1000181	S1000788	S1000783 needs repair, shipped to LHO! Spare used	
15			S1102629	spare, installed for testing?!	
14	Mode Cleaner Servo	D0901781	S1102625	IMC Cavity Locking	
13	LSC Demod Concentrator 1	D1100691	S1004005		
12	ASC Demod Concentrator 1	D1100696	S1103984		
11	LSC RFPD Interface	D1102079	S1200449		
10	WFS Interface	D1101906	S1200429		
9					
8	ISC 8 Channel Whitening Filter Chassis	D1002559	S1101612	ASC IMC WFS_A 24MHz	
7	WFS Quad I&Q RF Demodulator	D0902796	S1000991	ASC IMC WFS_A 24MHz	
6	Demodulator Patch Panel	D1100905			
5	WFS Quad I&Q RF Demodulator	D0902796	S1001024	ASC IMC WFS_B 24MHz	
4					
3	ISC 8 Channel Whitening Filter Chassis	D1002559	S1101571	ASC IMC WFS_B 24MHz	
2	Quad Differential to Single Ended Reciever	D1100482	S1202844		
1	DO NOT USE!				