




NOTES: (UNLESS OTHERWISE SPECIFIED)

REV	DATE	DCN #	DRAWING TREE #



- NOTES:
1. REMOVE ALL BURRS AND BREAK SHARP EDGES
 2. PART NUMBER (DRG NO., DASH NO., REVISION NO, SERIAL NO.) TO BE CLEARLY MARKED ON THE PART.
 3. PAINT MEDIUM BLUE, SHERWIN WILLIAMS POLANE T-PLUS POLYURETHANE ENAMEL #SW-F63TX-L-2822-5864.
 4. OXI-SOLV RUST INHIBITOR TO BE APPLIED TO BOTTOM SURFACE. DO NOT PAINT.
 5. PLUG TAPPED AND THRU HOLES DURING PAINT APPLICATION.
 6. FULL WELDED CONSTRUCTION
 7. STRESS RELIEVE BEFORE FINISH MACHINING
 8. REMOVE ALL SHARP EDGES

ITEM NO.	REQ.	SPARE	TOT. QUANTITY	PART NUMBER	DESCRIPTION	SUPPLIER
PARTS LIST						
UNLESS OTHERWISE SPECIFIED:				DATE	NAME	
DIMENSIONS ARE IN INCHES				6/20/02	KMASON	CALIFORNIA INSTITUTE OF TECHNOLOGY MASSACHUSETTS INSTITUTE OF TECHNOLOGY
TOLERANCES:				CHECKED		
XX ± .02						
XXX ± .005						
ANGULAR ± 1 DEG						
MATERIAL:				COMMENTS:	SIZE	DWG. NO.
STEEL					D	D020329-A-D
FINISH:					SCALE:	REV
SEE NOTES					D020329-A-SLDDRW	A
FILE NAME/LOCATION:						SHEET 1 OF 1