

1.5 (STOCK)

DEC1 9 1996

PSI DWG # V049-8-172

NOTES:

- 1. ALL SURFACES SHALL BE MACHINED OR MECHANICALLY POLISHED.
- 2. NO SNAGGING SHALL OCCUR WHILE WIPING WITH A CLEAN COTTON CLOTH.
- 3. PROTECT ALL SURFACES FROM SCRATCHES, GOUGES, AND TOOLING MARKS DURING HANDLING

