



DOCUMENT CHANGE NOTICE (DCN)

DOCUMENT No. (DOC-REV-GP. ID)	TITLE	NEW REV.
D010123-n/a-D	Left Side Block for 40m BS	A
D010124-n/a-D	Left Side Block for 40m PRM	A
D010125-n/a-D	Left Side Block for 40m SRM, MCC & MCF2	A
D010126-n/a-D	Left Side Block for 40m MCF1	A
D010127-n/a-D	Right Side Block for 40m BS, PRM & MCF1	A

CHANGE DESCRIPTION (FROM/TO):

D010128-n/a-D	Right Side Block for 40m SRM	A
D010129-n/a-D	Right Side Block for 40m MCC, MCF2	A
D010130-n/a-D	Ring for 40m Small Optics	A
D010131-n/a-D	Magnet Fixture for 40m Small Optics	A

Initial Release

REASON FOR CHANGE: n/a

ACTION: Incorporate change Attach DCN to drawing(s) Other action (specify):

DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)

DCN DISTRIBUTION (X=incl. docs)

- No hardware affected (record change only)
- List S/Ns which comply already:
- List S/Ns to be reworked or scrapped:
- List S/Ns to be built with this change:
- List S/Ns to be retested per this change:
-
-
-
-

	Barish	Coles
Coyne	Lazzarini	Lindquist
Raab	Sanders	Shoemaker
Stapfer	Tyler	Weiss
Whitcomb	Zydowicz	
Barton		
Jones		
Heefner		
X Romie		
Fritschel		

SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT? No Yes (If yes, enter Change Request number)

APPROVALS:	DATE	OTHER APPROVALS (specify)	DATE
ORIGINATOR: J. Romie	8-15-01		
TASK LEADER: J. Romie	8-15-01		
GROUP LEADER:			
DCC RELEASE:			