



DOCUMENT CHANGE NOTICE (DCN)

DOCUMENT No. (DOC-REV-GP. ID)	TITLE	NEW REV.
D960134-A-D	LOS Clamp, Suspension Block	B

CHANGE DESCRIPTION (FROM/TO): The clamp needs a sharp edge at the location where the wire leaves the clamp. Remove note 2. FILLETS: R .015 MAX. Add side view with "edge sharp" callouts on all four corners.

REASON FOR CHANGE: A radius on the corner of the clamp could cause noise.

ACTION: Incorporate change Attach DCN to drawing(s) Other action (specify):

DISPOSITION OF HARDWARE (IDENTIFY SERIAL NUMBERS)	DCN DISTRIBUTION (X=incl. docs)
<input type="checkbox"/> No hardware affected (record change only)	Althouse Barish Coles
<input type="checkbox"/> List S/Ns which comply already:	Coyne Lazzarini Lindquist
<input checked="" type="checkbox"/> List S/Ns to be reworked or scrapped: 102 parts from Schober, PC 263740	Raab Sanders Shoemaker
<input type="checkbox"/> List S/Ns to be built with this change:	Stapfer Tyler Weiss
<input type="checkbox"/> List S/Ns to be retested per this change:	Whitcomb Zydowicz
<input type="checkbox"/>	Bork Zucker
<input type="checkbox"/>	Barton Mason
<input type="checkbox"/>	Camp Jones
<input type="checkbox"/>	Fine
<input type="checkbox"/>	X Hazel

SAFETY, COST, SCHEDULE, REQUIREMENTS IMPACT? No Yes (If yes, enter Change Request number)

APPROVALS:	DATE	OTHER APPROVALS (specify)	DATE
ORIGINATOR: J. Hazel	4-30-98		
TASK LEADER: <i>M. Fine</i>	5/1/98		
GROUP LEADER: <i>Dennis Jayne</i>	4/30/98		
DCC RELEASE: <i>Andreas...</i>	5/4/98		