

INITIATOR HEK

DATE 10-9-98

LI90-E980565-00-D

**ENGINEERING CHANGE REQUEST (ECR)**

NEXT ASSEMBLY NO. F D972104

CUSTOMER DRAWING NO. 972131

DRAWING TITLE L160 SCISSORS TABLE TOP PLATE

REVISION: FROM E TO F



**HYTEC**  
INCORPORATED

DESCRIPTION OF CHANGE (Simple Phrase, Identify Dims If Possible): Change 2x .500 zone

C-2 to 2x .25

Item 2  $\Rightarrow$  1.5" pin now 0.75"

REASONS FOR CHANGE: Dowel pin going into 1.38" hole

D972119 zone C-6

IDENTIFY OTHER PARTS/GROUPS THAT INTERFACE WITH THE ABOVE (Required):

INTERFACE	RESPONSIBLE PARTY	INITIAL

NOTIFY COGNIZANT DESIGNER: P. ...

NOTIFY COGNIZANT ENGINEER: P. ...

APPROVED: P. ...