



ISC C1

ISC LVEA Equipment Room Rack C1
42 U

Rack Orientation In CER



Color Key

- 1 U Installed
- 1 U Ready for installation
- 1 U Built but not fully tested
- 1 U Still being built
- 1 U Not even started building


ISC C2

Color Key

Rack Orientation In CER




ISC LVEA Equipment Room Rack C2



ISC C3

ISC LVEA Equipment Room Rack C3

Rack Orientation In CER



Color Key



- 1 U Installed
- 1 U Ready for installation
- 1 U Built but not fully tested
- 1 U Still being built
- 1 U Not even started building

Status as of 13 June 2012

ISC C4

ISC LVEA Equipment Room Rack C4
42 U

Rack Orientation In CER



Color Key

- 1 U Installed
- 1 U Ready for installation
- 1 U Built but not fully tested
- 1 U Still being built
- 1 U Not even started building