

Alignment Monument Layout, LHO Y-End Station, BSC Mechanical Test Stands

When the Test Stand was reset it was found to be **0.008"** to the RIGHT (→) of centerline

Y-end VEA

