


3IFO SEI ISI Cross Check and Custody-31 March 2015





HAM1 Passive Stack Parts are being gathered to one location and will be tagged and documented ASAP. JLF

3IFO SEI HEPI Cross Check and Custody-30 March 2015

5?? HEPI Housing at OSW Will be moved to XMid under Ops.

16 HEPI Housings installed on H2. Will be stored in place until de-installed under Ops.



CRATE 1
HEPI 300 + 301
Actuators REMOVED

CRATE 2
302, 303
Act. removed


CRATE 3
304 305
ACTUATORS REMOVED

CRATE 4
306, 307
ACTUATORS REMOVED


CRATE 5
308, 309
Actuators Removed

CRATE 6
310, 311
Actuators Pulled













All actuators stored in
Mechanical Room.
Must be flushed on a regular basis.






**Pump Cart Controller issue to be dealt
with on Ops.**

3IFO SEI Masses Cross Check and Custody-30 March 2015



3IFO SEI Conflat and Feedthrough Cross-Check and Custody-30 Mar 2015



3IFO SEI Electronics Cross Check and Custody-27 March 2015

H2-SEI-C1



H2-SEI-C2



H2-SEI-C3



H2-SEI-C4



H2-SEI-C5



S1200882

H2-SEI-C6



S1200883

H2 SEI-C ET

H2 SEI-C ET